







Chairman 510






RU ИНСТРУКЦИЯ ПО СБОРКЕ
EN ASSEMBLY INSTRUCTIONS
DE AUFBAUANLEITUNG
FR INSTRUCTIONS DE MONTAGE
IT MANUALE D'USO
ES INSTRUCCIONES DE MONTAJE
CS NÁVOD K MONTÁŽI
KK ЖИНАУ ЖӨНІНДЕГІ НҰСҚАУЛЫҚ

1 pcs, 1 pcs, 1 pcs, 1 pcs, 1 pcs, 1 pcs, 1 pcs, 1 pcs, 1 pcs, 1 pcs, 1 pcs, 5 pcs, 6 pcs, 6 pcs

9 (M6x10) 4 pcs
 10 (M6x20) 8 pcs
 11 (M6x30) 6 pcs
 12 6 pcs



STEP 1
 ↓
STEP 2



CHAIRMAN
ПОМОГАЕТ РАБОТАТЬ

🌐 chairman.ru

✉ info@chairman.ru

📺 vk.com/chairman_chairs