



















Chairman Home 950

RU ИНСТРУКЦИЯ ПО СБОРКЕ
EN ASSEMBLY INSTRUCTIONS
DE AUFBAUANLEITUNG
FR INSTRUCTIONS DE MONTAGE
IT MANUALE D'USO
ES INSTRUCCIONES DE MONTAJE
CS NÁVOD K MONTÁŽI
KK ЖИНАУ ЖӨНІНДЕГІ НҰСҚАУЛЫҚ


1  1 pcs	2  1 pcs	3  1 pcs	4  2 pcs
5  1 pcs	6  1 pcs	7  5 pcs	8  (M6x55) 4 pcs
9  (M6x20) 4 pcs	10  (M6x25) 4 pcs	11  4 pcs	12  4 pcs





STEP 1
↓
STEP 2



5 fixed positions



max
120kg



CHAIRMAN
ПОМОГАЕТ РАБОТАТЬ

chairman.ru

info@chairman.ru

vk.com/chairman_chairs